

Sibley, Michael

From: Fowlow, Jeffrey
Sent: Thursday, March 12, 2015 10:59 PM
To: Sibley, Michael
Subject: FW: Odessa Biodiesel plant-Pictures 3/10/15

From: French, Gerald (ECY) [mailto:GEFR461@ECY.WA.GOV]
Sent: Tuesday, March 10, 2015 2:51 PM
To: Fowlow, Jeffrey; Liverman, Earl
Subject: Odessa Biodiesel plant-Pictures 3/10/15

Here a few pictures of pictures taken on 3/10/15.



Incompatible lab chemicals in cabinet



Leaking tote of sulfuric acid onto kitty litter



Leak of liquid from a tank



Drum inside of building



Drums inside of building



Fire extinguisher



Lime sacks



White crystals outside and west of building from pipe and valve marked as sodium methoxide inbound



Leaks of unknown liquid on floor.



White crystals on floor near totes holding citric acid and another tote holding caustic soda



Pump unit severely corroded



White crystal formed on outside of leaking tank

Jerry French
Department of Ecology, Eastern Regional Office
Hazardous Waste & Toxics Reduction Program
4601 North Monroe Street
Spokane, WA 99205-1295
(509) 329-3489
gefr461@ecy.wa.gov